	Eisenhower	Ford	Stevenson	Utica	IRC	ALC
SAFETY AND SECURITY						
Improved Controlled Front Entry	•	•	•	•	•	•
Upgrade Security Cameras	•	•	•	•	•	•
Improve Exterior Access Control	•	•	•	•	•	•
Replace PA System	•	•	•	•	•	•
INFRASTRUCTURE						
Resurfacing or replace areas of Parking Lots and/or Walkways*	•	•	•	•	•	
Roofing and/or Siding*	•	•		•		
Electrical Improvements*	•	•	•	•		
Flooring Replacement*	•	•	•			
Field Replacement and Improvements at Runkel/Swinehart stadiums	•	•	•	•		
Improve tennis courts	•	•	•	•		
Replace Site Lighting				•		
Upgrade Locker Rooms	•	•	•	•		
Improve lighting/sound in PAC	•	•	•	•		
Renovate Band Room	•	•	•			
Mechanical Improvements*	•	•	•	•	•	•
Furniture, Fixture and Equipment Replacement, as determined by building administration.	•	•	•	•	•	
TECHNOLOGY						
Upgrade Wireless System	•	•	•	•	•	•
Replacement of Equipment (i.e. computers, mobile devices and servers)	•	•	•	•	•	•
BUS REPLACEMENT						
Equip buses with Security Cameras, including general and special needs buses.	•	•	•	•	•	•
Purchase new buses annually as determined by long-range replacement program.	•	•	•	•	•	•

The 2018 Bond charts reflect an ongoing evaluation process and will be updated on a regular basis



*The improvements are targeted for specific areas of the school in need of replacement. The areas of the parking lot, roof, etc. are identified through a preventative cycle that is based on the district's strategic, long-range facilities management program.

More information on the areas targeted for improvements is available through the school office.









