

| | Beacon Tree | Beck | Browning | Burr | Collins | Crissman | DeKeyser | Dresden | Duncan |
|--|-------------|------|----------|------|---------|----------|----------|---------|--------|
| SAFETY AND SECURITY | | | | | | | | | |
| New Controlled Front Entry | | • | • | • | • | • | • | | • |
| Replace PA System | • | • | • | • | • | • | • | • | • |
| Improved Controlled Front Entry | • | | | | | | | • | |
| New Security Cameras | • | • | • | • | • | • | • | • | • |
| Upgrade Fire Alarm | | • | • | | | | | | |
| Improve Exterior Access Control | • | • | • | • | • | • | • | • | • |
| INFRASTRUCTURE | | | | | | | | | |
| Parking Lot Improvements* | • | • | | | • | | | | • |
| Roofing and/or Siding* | | | • | • | • | • | • | • | |
| Flooring Replacement* | | | | | • | | | | |
| Restroom Renovations* | | | • | • | | | | • | |
| Mechanical Improvements* | | | • | • | | | | • | |
| Furniture, Fixture and Equipment Replacement, as determined by building allocation and administration. | • | • | • | • | • | • | • | • | • |
| TECHNOLOGY | | | | | | | | | |
| Upgrade Wireless System | • | • | • | • | • | • | • | • | • |
| Replacement of Equipment (i.e. computers, mobile devices and servers) | • | • | • | • | • | • | • | • | • |
| BUS REPLACEMENT | | | | | | | | | |
| Equip buses with Security Cameras, including general and special needs buses. | • | • | • | • | • | • | • | • | • |
| Purchase new buses annually as determined by long-range replacement program. | • | • | • | • | • | • | • | • | • |

The 2018 Bond charts reflect an ongoing evaluation process and will be updated on a regular basis.




*The improvements are targeted for specific areas of the school in need of replacement. The areas of the parking lot, roof, etc. are identified through a preventative cycle that is based on the district's strategic, long-range facilities management program. More information on the areas targeted for improvements is available through the school office.

| | | | | |
|---|---|---|---|---|
|  |  |  |  |  |
| In Design | Bid Awarded | Under Construction | Project Completed | Project Completed |

| | Ebeling | Flickinger | Graebner | Harvey | Havel | Messmore | Monfort |
|--|---------|------------|----------|--------|-------|----------|---------|
| SAFETY AND SECURITY | | | | | | | |
| New Controlled Front Entry | • | | • | | • | • | • |
| Improved Controlled Front Entry | | • | | • | | | |
| New Security Cameras | • | • | • | • | • | • | • |
| Upgrade Fire Alarm | • | | | | | | |
| Replace PA System | • | • | • | • | • | • | • |
| Improve Exterior Access Control | • | • | • | • | • | • | • |
| INFRASTRUCTURE | | | | | | | |
| Parking Lot Improvements* | • | | | | | | • |
| Roofing and/or Siding* | • | • | • | • | • | • | • |
| Flooring Replacement* | | | | | | • | |
| Restroom Renovations* | | | | | | | |
| Mechanical Improvements* | • | • | | • | | • | • |
| Furniture, Fixture and Equipment Replacement, as determined by building allocation and administration. | • | • | • | • | • | • | • |
| TECHNOLOGY | | | | | | | |
| Upgrade Wireless System | • | • | • | • | • | • | • |
| Replacement of Equipment (i.e. computers, mobile devices and servers) | • | • | • | • | • | • | • |
| BUS REPLACEMENT | | | | | | | |
| Equip buses with Security Cameras, including general and special needs buses. | • | • | • | • | • | • | • |
| Purchase new buses annually as determined by long-range replacement program. | • | • | • | • | • | • | • |

The 2018 Bond charts reflect an ongoing evaluation process and will be updated on a regular basis.



*The improvements are targeted for specific areas of the school in need of replacement. The areas of the parking lot, roof, etc. are identified through a preventative cycle that is based on the district's strategic, long-range facilities management program.

More information on the areas targeted for improvements is available through the school office.



In Design



Bid Awarded



Under Construction



Project Completed



Project Completed

| | Morgan | Oakbrook | Plumbrook | Roberts | Schuchard | Schwarzhoff |
|--|--------|----------|-----------|---------|-----------|-------------|
| SAFETY AND SECURITY | | | | | | |
| New Controlled Front Entry | • | • | | • | • | • |
| Improved Controlled Front Entry | | | • | | | |
| New Security Cameras | • | • | • | • | • | • |
| Upgrade Fire Alarm | | | | | • | |
| Improve Exterior Access Control | • | • | • | • | • | • |
| Upgrade Fire Alarm | | | | | • | |
| Upgrade PA System | • | • | • | • | • | • |
| INFRASTRUCTURE | | | | | | |
| Parking Lot Improvements* | | • | | • | • | |
| Roofing and/or Siding* | • | • | • | • | • | • |
| Mechanical Improvements* | • | | | | • | • |
| Flooring Replacement* | • | | | | | |
| Furniture, Fixture and Equipment Replacement, as determined by building allocation and administration. | • | • | • | • | • | • |
| TECHNOLOGY | | | | | | |
| Upgrade Wireless System | • | • | • | • | • | • |
| Replacement of Equipment (i.e. computers, mobile devices and servers) | • | • | • | • | • | • |
| BUS REPLACEMENT | | | | | | |
| Equip buses with Security Cameras, including general and special needs buses. | • | • | • | • | • | • |
| Purchase new buses annually as determined by long-range replacement program. Phase One - 26 Buses | • | • | • | • | • | • |

The 2018 Bond charts reflect an ongoing evaluation process and will be updated on a regular basis



*The improvements are targeted for specific areas of the school in need of replacement. The areas of the parking lot, roof, etc. are identified through a preventative cycle that is based on the district's strategic, long-range facilities management program.

More information on the areas targeted for improvements is available through the school office.

| | | | | |
|---|---|---|---|---|
|  |  |  |  |  |
| In Design | Bid Awarded | Under Construction | Project Completed | Project Completed |

| | Switzer | West Utica | Wiley |
|--|---------|------------|-------|
| SAFETY AND SECURITY | | | |
| New Controlled Front Entry | | • | • |
| Improved Controlled Front Entry | • | | |
| New Security Cameras | • | • | • |
| Improve Exterior Access Control | • | • | • |
| Replace PA System | • | • | • |
| INFRASTRUCTURE | | | |
| Parking Lot Improvements* | • | • | |
| Roofing and/or Siding* | • | • | • |
| Flooring Replacement* | | | |
| Restroom Renovations* | | • | • |
| Mechanical Improvements* | • | • | • |
| Furniture, Fixture and Equipment Replacement, as determined by building allocation and administration. | • | • | • |
| TECHNOLOGY | | | |
| Upgrade Wireless System | • | • | • |
| Replacement of Equipment (i.e. computers, mobile devices and servers) | • | • | • |
| BUS REPLACEMENT | | | |
| Equip buses with Security Cameras, including general and special needs buses. | • | • | • |
| Purchase new buses annually as determined by long-range replacement program. | • | • | • |

The 2018 Bond charts reflect an ongoing evaluation process and will be updated on a regular basis



*The improvements are targeted for specific areas of the school in need of replacement. The areas of the parking lot, roof, etc. are identified through a preventative cycle that is based on the district's strategic, long-range facilities management program.

More information on the areas targeted for improvements is available through the school office.



In Design



Bid Awarded



Under Construction



Project Completed



Project Completed